

Reported Fault: *call from customer

Unit makes high pitched noise

In High mode there is nothing but in low mode there is a high noise
Customer put the phone next to the unit and i could hear the noise

i asked the check the lamp and it done 250 hours
Th noise comes and goes , sometimes it high and sometimes it lower, the noise seems to come from
the front and it it not as a fan noisem it more nose and HDD of a PC
advised bu phit the is either the ballast or the lamp

Fault(s) Found: Possible NFF as per nature of the fault*
Precautionary repair

Repair Details: The parts listed below have been replaced, followed by soak testing and function checks. Your
product has been checked, tested and confirmed to be operating at the expected standard. A
function check has been carried out.

Parts Replaced: 1 x 147459233 (POWER UNIT (FOR LAMP 280W))
1 x A2184763A (MOUNTED C.BOARD, G MOUNT)

Technician: The technician responsible for your unit was Tom B.